nter overview	printer IMP-01 2B2	PRINTING	!!! heatbed 100→100 °C	% <u>₹</u> Za	axis 1.4mm 👩 material /	ABS
ojects	2:04:59 PM	STATE_CHANGED READY	MARLIN			new state from event
ontrol	2:04:56 PM	EMIT	CONNECT	21	SEND_JOB_INFO	
mmand	2:04:56 PM	ACCEPTED	CONNECT	21		new state from event
ettings pload Project	2:04:56 PM	REJECTED	WUI	21	SEND_JOB_INFO	Command error
	2:04:55 PM	EMIT	CONNECT	20	SEND_JOB_INFO	
	2:04:55 PM	ACCEPTED	CONNECT	20		new state from event
	2:04:55 PM	REJECTED	WUI	20	SEND_JOB_INFO	Command error
	⊟{ "error": "Cann }	ot get job info, when there is no job in progres	s."			
	2:04:54 PM	REJECTED	WUI	19	SEND_JOB_INFO	Command error
	⊟{ "error" : "Cann }	ot get job info, when there is no job in progres	s."			
	2:04:54 PM	EMIT	CONNECT	19	SEND_JOB_INFO	
	⊟{ "args": "{"job }	_id": 39}"				